

River Survey Worksheet v2

River	Location	Property ID	Latitude	Longitude	Picture #	Notes	Date	Team:
Green River	Green River Road	(1804 GRR)	N42°45.726	W72°43.706	pgRR01-04	7 large trees on side of river channel, tall slope w/ power lines sloughed off (also, construction remnant of logs; toilet tank along access rd)	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(1836 GRR)	N42°48.820	W72°43.711	pgRR05	1 large, 2 small trees in side channel, only noting if here for more substantial piles	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(1932 GRR)	N42°48.818	W72°43.613	pgRR06	4 medium trees	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(2402 GRR)	N42°48.766	W72°43.332	pgRR07-08	2 debris piles alongside road, 20' long, by 4' wide x 4' tall (over an apparently washed out metal culvert (non-functioning today))	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(2418 GRR)	N42°48.711	W72°43.298	pgRR09-13	long stretch of trees downed on the bank far side of river, plus final picture on road side (small bundle in roots)	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(2444 GRR)	N42°48.663	W72°43.171	pgRR 14-15	Huge debris pile w/ at least 7 major logs, just before (upstream of) the bridge West of Perry Rd. BR #16	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(2455 GRR)	N42°48.661	W72°43.118	pgRR 16-18	Different angle of same > Huge debris pile w at least 7 major logs, just before the bridge West of Perry Rd. BR #16	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(2455 GRR)	N42°48.661	W72°43.118	pgRR19 X pgRR20	Opposite side (downstream) of Bridge #16. Evergreens on large bank slide. GRR20--Note bridge guardrail hole for road commissioner	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road	(2465 GRR)	N42°48.626	W72°43.094	pgRR 21-23	3 large trees before a culvert that has been replaced at end of Perry Road (not on Green River directly, but empties there)	5/5/2012	Gretchen Becker & Edee Edwards
Green River	Green River Road				1,2	Behind Merle Eggert's House, Trees and stumps in Green River and bank	5/5/2012	Earl & Pat Holz
Green River	Green River Road		N42°48.2500	W72°42.5713	3	East of Merle Eggert's house	5/5/2012	Earl & Pat Holz
Green River	Green River Road		N42°48.3126	W72°42.4931	4,5	Large pile, Hemlock in channel plus debris on flat in river	5/5/2012	Earl & Pat Holz
Green River	Green River Road		N42°48.2065	W72°42.1200	6,7,8,9,10	Debris field 100 feet long, note red leaching in to river, stinks, 1/2 mile east of Merle Eggert's house	5/5/2012	Earl & Pat Holz
Green River	Green River Road		N42°48.2509	W72°42.8205	11,12,13	10 trees on far bank, across from 63 Old Green River Road (near mail box)	5/5/2012	Earl & Pat Holz

River Survey Worksheet v2

Hinesburg Brook	Hale Road	5615 W/44			14	Large debris field on river bank adjacent to mail box 4615 Green River just before bridge	5/5/2012	Earl & Pat Holz
CR	Hale Road	GRR			15.16	Behind Marie Eggert's House, Trees and stumps in Green River and bank	5/5/2012	Earl & Pat Holz
Hinesburg Brook	Hale Road		N42°49.2033	W72°41.0453	17	Culvert Bridge, Debris up stream	5/5/2012	Earl & Pat Holz
Hinesburg Brook	Hale Road		N42°48.9119	W72°42.9139	18	Culvert Bridge, Debris down stream	5/5/2012	Earl & Pat Holz
Hinesburg Brook	Hale Road		N42°48.9119	W72°42.9139	19.20.21	Culvert Bridge, Broken foundation	5/5/2012	Earl & Pat Holz
East Branch North River	Rte. 112	Maltese			Rte. 112 - 1&2	2 large trees across water 90 degree angle	5/5/2012	Ron Smith & Margo Dunn
East Branch North River	Rte. 112	6920 Rte. 112			Rte 112 - 3-5	4 trees at 90 degree angle in river, potential blockage	5/5/2012	Ron Smith & Margo Dunn
East Branch North River	Rte. 112	North of Blue house			Rte 112 - 6-9	Large trees falling, landslide	5/5/2012	Ron Smith & Margo Dunn